

HOPATCONG UC&M SUBSTATION SNOW REMOVAL AGREEMENT

The plowing of substations will begin when a need is determined by the UC&M management group. The priority substations are indicated in each of the areas with the department responsibility listed with the substation. The plowing of substations will consist of opening the driveway to each substation to allow entrance to the gate. The gate area should be cleaned to allow for gate opening. The clearing of additional snow inside the substation will be determined by the lead UC&M supervisor. The lead UC&M supervisor in each area will direct the coordination of the priority and non-priority substation with associated districts and resources. Plowing inside the substation confines will be determined by the lead UC&M supervisor and coordinated with associated districts. When snowfall accumulations require additional aid the UC&M supervisor will contact adjoining districts and other resources to plan further snow removal. When the need arises for outside contractors, the lead UC&M supervisor will contact the facilities manager or supervisor to arrange contractors to aid in snow plowing and removal of substations.

Lead Contacts

Name	Office Number	Pager Number	Cell Number	Home Number
Alan Frey (Hopatcong)	973-989-2223 3-210-2223	973-612-1037	201-787-6078	973-398-5898
Tom Bodine (Newton)	973-300-2901 3-202-2901	973-612-1017	973-766-5111	570-897-0205
Tom Bodine (North Dover)	973-537-2614 3-214-2614	973-612-1017	973-766-5111	570-897-0205
Roy Cooper (West Wharton)	973-644-5697 3-230-5697	973-612-1071	862-881-1932	973-361-5165

Initiate plowing of West Wharton only by Roy Cooper.

Zone 1

West Wharton*-Fleet HEO**
Morris Street
Dickerson
West Denville
Mt. Fern
Denville

Zone 2

Beach Glen
Rockaway
Fleetwood
East Dover
Dover
Thatcher
Hurdtown

HOPATCONG UC&M
SUBSTATION SNOW REMOVAL AGREEMENT (continued)

Zone 3

Newton* - Newton District
Holiday Lakes
Branchville
North Newton
East Newton
Andover
Mohawk

Zone 4

Franklin*-Newton District
Vernon*- Newton District
Cozy Lake
Sparta
Hamburg Boro
Sussex
Woodruff's Gap

Zone 5


Flanders*-UC&M
Kenvil
Landing
Netcong
Mt Arlington
Hopatcong
Hopatcong Sw. Pt.
Saxton Falls


Zone 6


Chester*-N. Dover HEO
Mendham-K&M Contracting
Peapack
Bernardsville
Long Lines
Great Cross Roads
Chambersbrook
Somerset
Hackettstown
Newburg
Allamuchy


* Indicates priority

** To include West Wharton substation road, parking area, transformer yard & roadways,
Wharton Stores (98 N. Main Street) fenced area as requested by Stores.


JCP&L Substation
Manager


Date


Local Union # 327
President/Vice President


Date